

# SERVICE INFORMATION

Date: 22/05/2010

Subject:

Water ingress through oil reservoir breather

altek International Ltd  
The Office  
Timaru Farm  
Barton Road  
Elsham, Brigg  
North Lincolnshire  
England  
DN20 0LS.  
Tel + 44 (0)1652 688 889  
Fax + 44(0) 05603 129 813  
[sales@altekinternational.com](mailto:sales@altekinternational.com)  
[www.altekinternational.com](http://www.altekinternational.com)

We have found that in certain conditions it is possible that water can leak into the oil reservoir which in turn causes the oil to turn milky.

**ACTION:** All caps of type "A" below should be replaced with a cap of type "B" at the earliest possible time / next service visit.

